

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 6,887,594 B2  
APPLICATION NO. : 10/773373  
DATED : May 3, 2005  
INVENTOR(S) : Li et al.

Page 1 of 1


It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 6, line 24, "wherein the amount of tantalum oxide is at least 50." should be changed to --wherein the amount of tantalum oxide is at least 50 mol%--

Column 6, line 27, "wherein the Al<sub>2</sub>O<sub>3</sub>" should be changed to --wherein the Al<sub>2</sub>O<sub>3</sub>--

Signed and Sealed this

Tenth Day of April, 2007



JON W. DUDAS  
*Director of the United States Patent and Trademark Office*